

GENERAL ADMINISTRATION DIVISION  
Report No. 4

OGDENSBURG CITY SCHOOL DISTRICT  
OGDENSBURG, NEW YORK

---

SUBJECT: Annual School Fire Inspection Report

DATE: July 1, 2020

REASON FOR BOARD CONSIDERATION:

The Board of Education must be informed of the outcome of the District's Annual Fire Inspection.

FACTS AND ANALYSIS:

Since our District's fire inspection has been completed for all of our school facilities, the Board of Education must be informed regarding results of the inspection under Education Law 807-a. Mr. James McCarthy, Director of Facilities III, is present this evening to review the District's Annual Fire Inspection Report with the Board of Education.

RECOMMENDED ACTION:

Moved by \_\_\_\_\_ and supported by \_\_\_\_\_ that, having the approval of the Superintendent of Schools, the Board of Education of the Ogdensburg City School District does hereby accept the Annual Fire Inspection Report on the 1<sup>st</sup> day of July 2020.

APPROVED FOR PRESENTATION TO THE BOARD:

  
Superintendent

KK/alf  
Attachment

# **NCE Environmental Consultants**

December 5, 2019

Mr. Jim McCarthy  
Director of Facilities III  
Ogdensburg City School District  
1100 State St.  
Ogdensburg, New York 13669

Re: 2019 Fire Inspections

Dear Mr. McCarthy:

I have completed the fire inspections of all the buildings in the district and the following violations were noted. It is required that these violations be corrected in order to receive a certificate of occupancy.

**Garage 1**– No violations noted.

**Garage 2**- No violations noted.

**Garage 3**- No violations noted.

**Garage 4**- No violations noted.

**Garage 5**- No violations noted.

**Garage 6**- No violations noted.

**Central Receiving** – No violations noted.

**Concession Stand** – No violations noted.

**Press Box** – No violations noted.

**Track Shed** - No violations noted.

**Snack Barn** - No violations noted.

**36173 NYS Rt. 12E Clayton, New York 13624  
315-654-5077**

**Golden Dome** – No violations noted.

**OFA**

1. Item 12E1 Bad cord end in guidance.
2. Item 12K1 Cover plate missing in Faculty lounge room 226.
3. Item 17D2 Exit light by pool not working.

**Kennedy School**

1. Item 9D1 Items stored within 2' of the ceiling in room 51.
2. Item 10A2 Exit directions missing in room 33.
3. Item 12J1 Improper use of an extension cord in room 63.
4. Item 14C2 Magnets/wedges being used to keep doors open throughout the building.
5. Item 17C2 Decorations covering doors and windows throughout the building. Really excessive on the door of room 5.

**Metal Storage Shed Kennedy**- No violations noted.

**Madill School**

1. Item 12K1 Bad cord end in kitchen.
2. Item 14C2 Magnets being used to keep doors open in various locations.

**Madill Storage Building** – No violations noted. Major improvement in the organization of material and equipment in this location.

Very noticeable that a large effort was placed on maintaining the emergency lights.